


1975 Alfasud 1.3 ti - The return of the King


Interior Restoration

Major work was focused on the dashboard. Brittle and thin like paper plastics showed their age ... We decided to cover the dashboard on leather and hand stitch it.

In addition the steering wheel was taken apart as the spongy material was literally collapsing. It was taken to bare metal and using new materials, the shape was regenerated.

You can see the results!







We are moments away before the Alfasud leaves the bodyshop under new life!